


# ASSEMBLY & INSTALLATION INSTRUCTIONS

C125

Pangea Torchiere 241109

---



HUBBARDTON FORGE.

MODERN AMERICAN BLACKSMITHS | FINE, HAND CRAFTED LIGHTING  
CASTLETON, VERMONT USA | HUBBARDTONFORGE.COM

55936

1 OF 3

**Component Parts**

- A      Base**
- B      Center Section**
- C      Top Section**
- D      Male Connector**
- E      Female Connector**
- F      Shade**
- G      Washer (4)**
- H      Knurled Balls (4)**




Pangea Torchiere 241109

**CAUTION: FAILURE TO INSTALL THIS FIXTURE PROPERLY MAY RESULT IN SERIOUS PERSONAL INJURY OR DEATH AND PROPERTY DAMAGE.** We recommend installation by a licensed electrician. This product must be installed in accordance with applicable installation code(s), by a person familiar with the construction and operation of the product and the hazards involved.\*

**Caution:** Do not exceed maximum wattage noted on fixture. Use only recommended bulbs with fixture.

## Assemble Fixture (Figure 1)

1. Carefully unpack the fixture from the carton.
2. Feed wires from top section (C) through center section (B). Thread center section (B) onto top section (C).
3. Connect female connector (D) with male connector (E).
4. Push connector (D & E) into center section (B). Thread center section (B) onto base (A).
5. Place shade (F) onto top section (C), align holes with studs. Place washers (G) over studs. Secure with knurled balls (H).
6. Install bulb (not included).
7. Plug in power cord.



(Figure 1)

If you need further assistance, or find that you are missing any parts, please contact the dealer from which you purchased this product. We hope you enjoy your fixture!

**\* Hubbardton Forge will not be liable for injury or damage caused by improper installation, lamping or use of this fixture.**