

American Brass & Crystal


Casting a Finer Light



CH9102

American Brass and Crystal provides the finest quality components manufactured, designed and finished by master artisans. We take great pride in our production abilities and we empower our valued customers with the ability to custom create the light that is perfect for them.

Enclosed are detailed instructions on how to properly assemble and install your chandelier. If you have any questions please call our toll free customer service hotline at: **1-(877)-465-5617**

 American Brass and Crystal
835 Lehigh Avenue, Union, NJ 07083


www.abclighting.net



American Brass & Crystal

Casting a Finer Light


Crystal Component Detail



Letter: A
Quantity: 4

1.5" Drop w/14mm Octagon


Connect to the inner hole on all 4 arms.



Letter: B
Quantity: 4

1.5" Drop w/4 hole-14mm Octagon and 9-14mm Octagon Strand from right.


Connect to the outer hole on all 4 arms using the long thin pin. Leave the strand to hang until all are hung then connect strand to adjacent arm at 4 hole octagon.



Letter: C
Quantity: 16

1.5" Drop w/14mm Octagon

Connect to all 4 stations around each of the 4 bobeches.



Letter: D
Quantity: 4

1.5" Drop w/14mm Octagon

Connect to all 4 stations around top cover.

Note: Diagrams are just representative

Crystal Trimming Directions

Begin trimming your sconce after all of the electrical connections have been made, the lights have been tested and the sconce is in good working order. Begin trimming in Alphabetical order. Do not unwrap the next letter until previous one is complete.




DIAGRAM 1



Refer to Diagram 1 when connecting the loose chain to the 4-hole octagon on the same lettered station on the adjacent arm.

You will see a (☆) at all positions where such a connection must be made.