




Mounting Instruction



NOTE: Diagrams above are just representative.

1. mounting block 2. main body 3. candle pipe
4. nipple

Electrical Diagram



Overhead View

All electrical components must be installed by a licensed electrician and in accordance with the National Electric Code and the appropriate local electrical codes.

American Brass & Crystal


Casting a Finer Light



WS2082

American Brass and Crystal provides the finest quality components manufactured, designed and finished by master artisans. We take great pride in our production abilities and we empower our valued customers with the ability to custom create the light that is perfect for them.

Enclosed are detailed instructions on how to properly assemble and install your sconce. If you have any questions please call our toll free customer service hotline at: **1-(877)-465-5617**

 American Brass and Crystal
835 Lehigh Avenue, Union, NJ 07083

www.abclighting.net





Letter: A
Quantity: 1
 (40mm Ball w/
 6-14mm-Oct)
 Connect to bottom
 Center finial.




Letter: B
Quantity: 1
 Connect to back hole of both arms.



3-14mm +
 3HL + 2.5" Drop (8-14mm Drape) 3-14mm +
 3HL + 2.5" Drop



Letter: C
Quantity: 1
 Connect to the front hole of both arms.



3 HL + 1-14mm (17-14mm Drape) 3 HL + 1-14mm
 + 3 HL + 2.5" Drop (17-14mm Drape) + 3 HL + 2.5" Drop




Letter: D
Quantity: 8
 (3"U w/14mm Oct.)

Connect to front
 4 holes only on
 both bobeches



Letter: E
Quantity: 2
 (3hl + 16-14mm double
 drape + 3 hole + 3"U)
 Connect top to crown
 cover and bottom to
 back two holes of
 bobèche beneath it.



Letter: CR1
Quantity: 1 Connect to top crown scrolls.



(3hl + 2-14mm + 2.5" Drop) (4-14)+3HL+(4-14) (2-14+3" Drop) (4hl + 2-14mm + 2.5" Drop) (4-14)+3HL+(4-14) (2-14+3" Drop) (3hl + 2-14mm + 2.5" Drop)