



1718 W. Fullerton Chicago, IL 60614
 Ph: 773.770.1195 • Fax: 773.935.5613
 www.PureEdgeLighting.com • info@PureEdgeLighting.com
 © 2016 PureEdge Lighting. All Rights Reserved.

Installation Instructions for **Completed Light Channel .3 Surface Mount with Lazer Strip**


LCS.3_—




IMPORTANT INFORMATION

- This instruction shows a typical installation.

SAVE THESE INSTRUCTIONS!



Section One: Install the Light Channel





1: Determine the location of the Light Channel .3 Surface Mount.

2: Mark the location of the mounting clips evenly on a straight line. Mounting clips must be maximum 24" apart from each other.


NOTE: Steps 3 and 4 are for drywall mounting. Omit these steps if mounting to a wood surface directly.

3: Tap the anchors onto the marked locations up to the threaded portion with a hammer.

4: Screw in the threaded portion of the anchors with a Phillips screwdriver.




5: Align the mounting clips to the anchors and secure each clip to each anchor by tightening the #8 screws.



6: Snap the light channel assembly to the mounting clips.

7: Cut the end of the power cord that is going to be connected to power and discard the unused connector. Strip the ends of the wires.

NOTE: Follow the instructions provided with the power supply to power the light channel.



General Wiring Diagram

