



1718 W. Fullerton Chicago, IL 60614  
 Ph: 773.770.1195 • Fax: 773.935.5613  
 www.PureEdgeLighting.com • info@PureEdgeLighting.com  
 © 2016 PureEdge Lighting. All Rights Reserved.


## Installation Instructions for **Track Surface L-Connector, 1-Circuit**

**TS24-1C-L\_C-WH**


### IMPORTANT INFORMATION

- This instruction shows a typical installation.

**SAVE THESE INSTRUCTIONS!**





## Install the L-Connector



**1:** L-Connectors join two track sections together in a 90 degree angle and either conduct the power from one track to the other (LC) or isolate the power from one track to the other (LNC).

- 2:** Slide the track over the joiner bracket of the L-Connector.
- 3:** Tighten the two #4-40 set screws on the joiner bracket using a 0.05" Allen wrench.
- 4:** Repeat steps 2 and 3 for the other end of the L-Connector.



**5:** For the conductive sides of the L-Connector, place the straight conductive connector where the tracks are joined. Tighten the slotted screws with a flat-head screw driver to secure in place.