

To Operate

Surface Mount and Freestanding


TO POWER ON/OFF

Touch the light post anywhere above the line on the post to operate. A quick touch will turn the light on and off.

TO ADJUST BRIGHTNESS

Touching and holding the light post anywhere above the line on the post will adjust the continuous dimming.

NOTE: Shade is not adjustable.




Touch light post
at any point in this
range to operate.


Ruth

Freestanding instructions
by Most Modest™

Included in package:



Ruth Freestanding
light fixture




Power Supply
24V, 65W

Step 1

Remove the light from the box
and place on desired surface.

Step 2

Connect the light to the
provided power supply and
plug the power supply into a
120V source.




NOTICE: Class I LASER Product.

Ruth


by Most Modest™

Surface mount instructions


Included in package:



Ruth surface mount light fixture



Power Supply
24V, 65W



Ruth surface mount clamp





1/4"-20 Button Head Screws (2)

Tools needed:

3-1/2" diameter hole saw
5/32" allen wrench

Step 1


Prepare the surface by cutting a 3-1/2" diameter hole in the worksurface. Remove the light from the box and route the power cord through the hole in the worksurface. Place the lamp into the hole, being mindful to not pinch the cord.



Step 2

From the underside of the worksurface, install the lower clamp using the provided 1/4"-20 Button Head Screws. Use a 5/32" allen wrench to tighten the two screws until the clamp holds firmly to the underside of the worksurface.

USB version only: Rotate lamp to align USB ports to the desired position prior to tightening screws.



Pro Tip: It can be helpful to have a second person hold the light in place while clamping to ensure orientation stays as desired and the light does not fall over.

Step 3

Connect the light to the provided power supply and plug the power supply into a 120V source.

