


hollis+morris

stala pendant

product installation + specifications



dimensions + installation

See Tearsheet for dimensions and general specifications

1. Locate desired ceiling location.
2. Have a certified electrician supply 120V power to driver.
3. Feed coax cable through Junction Plate, tie a knot in the cable behind plate at desired drop height.
4. Connect coax*** to driver and close junction box with junction plate and provided #8-32 Flat head screws.

*** COAX CABLE

Coax cable requires stripping of outer and inner coatings to access positive and negative connection wires

