American Brass & Crystal Casting a Finer Light

American Brass & Crystal

Casting a Finer Light



FM2015

American Brass and Crystal provides the finest quality components manufactured, designed and finished by master artisans. We take great pride in our production abilities and we empower our valued customers with the ability to custom create the light that is perfect for them.

Enclosed are detailed instructions on how to properly assemble and install your chandelier. If you have any questions please call our toll free customer service hotline at: 1-(877)-465-5617

American Brass and Crystal
835 Lehigh Avenue, Union, NJ 07083 www.abclighting.net



Crystal Component Detail



Letter: A Quantity: 1

40mm Ball w/14mm Oct.

Connect to bottom center Finial



Letter: B Quantity: 40


2" Drop w/14mm Oct.

Connect to back and front holes on arms.

Connect to 6 holes around each of the bobeches.

Crystal Trimming Directions

Begin trimming your chandelier after all of the electrical connections have been made, the lights have been tested and all is in good working order. Begin trimming in Alphabetical order. Do not unwrap the next letter until the previous one is complete.



Note: Diagrams are just representative