


 **SCHONBEK** | 1870










**CHANTANT**  
**CH0812N- \_\_ \_ O**








**T**HIS DESIGN IS THE PROPRIETARY  
TRADE DRESS/TRADEMARK OF  
W SCHONBEK LLC.

3 Lights  
Diameter: 10-1/2"  
Height: 24-1/2"  
Hanging Weight: 10lbs.



 **SCHONBEK** | 1870




|   |   |   |          |   |   |   |   |   |
|---|---|---|----------|---|---|---|---|---|
|  |  |  | <b>S</b> |  |  |  |  |  |
| MAX <b>50</b> W   | 110-120 V   |  |          |   |   |   |   |   |











1 X  : 1746









3 X  : GU10 50W MAX 



11




- 12 A1 - A3
- 13 B1 - B3
- 14 C1 - C3
- 15 D1 - D10
- 16 E1 - E10
- 17 F1 - F15



After hanging all trim, remove labels from crystals. If residue remains, wipe off crystal with a soft, dry cloth.

 **SCHONBEK** | 1870










**CHANTANT**  
**CH0812N- \_\_ \_\_ R**







**T**HIS DESIGN IS THE PROPRIETARY  
TRADE DRESS/TRADEMARK OF  
W SCHONBEK LLC.


3 Lights  
Diameter: 10-1/2"  
Height: 24-1/2"  
Hanging Weight: 10lbs.

 **SCHONBEK** | 1870



|   |   |   |          |   |   |   |   |   |
|---|---|---|----------|---|---|---|---|---|
|  |  |  | <b>S</b> |  |  |  |  |  |
| MAX <b>50</b> W   | 110-120 V   |  |          |   |   |   |   |   |
















1 X  : 1746









3 X  : GU10 50W MAX 



11



- 12 A1 - A3
- 13 B1 - B3
- 14 C1 - C3
- 15 D1 - D10
- 16 E1 - E10
- 17 F1 - F15



After hanging all trim, remove labels from crystals. If residue remains, wipe off crystal with a soft, dry cloth.