

Instructions for electrician **STEPS 2 - 6**




All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.



- **3** Attach crossbar to outlet box.
- 4 Slip screw collar and metal canopy over chain. Determine the suspension length of the fixture and cut chain, if necessary. Use two connecting links to attach chain to chandelier loop and ceiling loop.
- **5** Insert stem wire through chain and ceiling loop. Connect wire. Fixture MUST be grounded. Check distance from ceiling to loop to assure canopy assembly will be flush against ceiling and tighten with lock nut. Attach canopy to ceiling with screw collar.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from fixture.


CLOSE TO CEILING VERSION



- **3** Remove set screw from loop with tool provided. Remove all component parts from loop to seating ring. Remove threaded hex nipple and nut from assembled canopy. Run wires up through cover, canopy and component parts and tighten hex nut.
- **4** Attach cross bar to outlet box. Connect wire.
- **5** Attach canopy to ceiling with mounting balls, thereby retaining complete fixture against ceiling.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from fixture.


CHANDELIER 5344- ___ TRIM DIAGRAM

(Finish Option)






See diagram on back page Follow steps in exact order Save this trim diagram for future reference




Instructions for crystal trimming **STEPS 7 - 14 HANG CRYSTAL** #9764/1 **WITH FLAT** 7 SIDE FACING **FRONT** You will need 4 - B10 25 Watts Recommended 40 Watts Max Install bulbs and be sure to test fixture BEFORE trimming. 8 8 #9934 #9934 14 #9764/1 #9764/1 14 TO LETTER "D" TO LETTER "D" ON NEXT ARM ON NEXT ARM Ε Ε **(13**) **(13**) **12** D **11** 9 9 11 N10124-** N10124-** **(10**) Tighten With **Tool Provided.** 5344-___

Instructions for electrician **STEPS 2 - 6**




All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.

PENDANT VERSION



- **3** Attach crossbar to outlet box.
- 4 Slip screw collar and metal canopy over chain. Determine the suspension length of the fixture and cut chain, if necessary. Use two connecting links to attach chain to chandelier loop and ceiling loop.
- **5** Insert stem wire through chain and ceiling loop. Connect wire. Fixture MUST be grounded. Check distance from ceiling to loop to assure canopy assembly will be flush against ceiling and tighten with lock nut. Attach canopy to ceiling with screw collar.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from

CLOSE TO CEILING VERSION



- **3** Remove set screw from loop with tool provided. Remove all component parts from loop to seating ring. Remove threaded hex nipple and nut from assembled canopy. Run wires up through cover, canopy and component parts and tighten hex nut.
- 4 Attach cross bar to outlet box. Connect wire.
- **5** Attach canopy to ceiling with mounting balls, thereby retaining complete fixture against ceiling.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from fixture.


CHANDELIER 5344- R TRIM DIAGRAM

(Finish Option)






See diagram on back page Follow steps in exact order Save this trim diagram for future reference




Instructions for crystal trimming **STEPS 7 - 14 HANG CRYSTAL** 9764/1 **WITH FLAT** 7 SIDE FACING You will need 4 - B10 **FRONT** 25 Watts Recommended 40 Watts Max Install bulbs and be sure to test fixture BEFORE trimming. 8 8 9934 9934 9764/1 9764/1 14 14 TO LETTER "D" ON NEXT ARM TO LETTER "D" ON NEXT ARM Ε Ε 11 11 13 **(13**) **12** 12 D 9 (10) NR10474-** 9 NR10474-** **Tighten With Tool Provided.** 5344-___ R

Instructions for electrician STEPS 2 - 6




All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.

PENDANT VERSION



- **3** Attach crossbar to outlet box.
- 4 Slip screw collar and metal canopy over chain. Determine the suspension length of the fixture and cut chain, if necessary. Use two connecting links to attach chain to chandelier loop and ceiling loop.
- **5** Insert stem wire through chain and ceiling loop. Connect wire. Fixture MUST be grounded. Check distance from ceiling to loop to assure canopy assembly will be flush against ceiling and tighten with lock nut. Attach canopy to ceiling with screw collar.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from fixture.

CLOSE TO CEILING VERSION



- Remove set screw from loop with tool provided. Remove all component parts from loop to seating ring. Remove threaded hex nipple and nut from assembled canopy. Run wires up through cover, canopy and component parts and tighten hex nut.
- 4 Attach cross bar to outlet box. Connect wire.
- **5** Attach canopy to ceiling with mounting balls, thereby retaining complete fixture against ceiling.
- **6** Screw bulbs into sockets. Test power to insure proper wiring before hanging trim from fixture.




TRIM DIAGRAM

(Finish Option) (Trim Option)



SCHONBEK®

See diagram on back page Follow steps in exact order Save this trim diagram for future reference



Instructions for crystal trimming **STEPS 7 - 14 HANG CRYSTAL** #9764/1-** **WITH FLAT** 7 **SIDE FACING** You will need 4 - B10 **FRONT** 25 Watts Recommended 40 Watts Max Install bulbs and be sure to test fixture BEFORE trimming. 8 8 #9934-** #9934-** #9764/1-** #9764/1-** 14 14 TO LETTER "D" ON NEXT ARM TO LETTER "D" ON NEXT ARM Ε 11 **11 13**) **(13**) D **12** 9 (10) 9 N10474**-** N10474**-** **Tighten With Tool Provided.** 5344-__ __ __