



1718 W. Fullerton Chicago, IL 60614  
 Ph: 773.770.1195 • Fax: 773.935.5613  
 www.PureEdgeLighting.com • info@PureEdgeLighting.com  
 © 2016 PureEdge Lighting. All Rights Reserved.


## Installation Instructions for **Track Surface Mount End Power Feed, Single Circuit with 4' Plenum Rated Cable**

TS24-EP1-4FTC\_

### IMPORTANT INFORMATION


- This instruction shows a typical installation.
- The fixtures used with the PureEdge Lighting systems must be identified for use with the corresponding PureEdge Lighting systems.

**SAVE THESE INSTRUCTIONS!**




## Install the Plenum Rated Cable

**A**




**1:** If not pre-installed, feed the plenum rated cable through the end cap.

**B**




**2:** Push the end cap into the end of the track.

**C**



**3:** Place the Power Feed Adapter into the track. Tighten the slotted screw of the Power Feed Adapter using a flat-head screw driver to secure in place.

**4:** Tighten the strain relief on the cable using a flat-head screw driver.



**5:** Route the cable to the remote power supply.

**6:** Connect the low voltage +24VDC power supply wire to the red wire of the Power Feed Adapter cable using a wire nut.

**7:** Connect the low voltage -24VDC power supply wire to the black wire of the Power Feed Adapter cable using a wire nut.

**8:** Refer to the instructions provided with the power supply to power the fixture.

**NOTE:** Refer to the instructions provided with the TS24 Track Surface to complete the installation.

## General Wiring Diagram

