

GLACIER PERFORATED


MR16 Hanging Down Light



DESCRIPTION

Based on our original Glacier Hanging Down Light, the Glacier Perforated Hanging Down Light offers a modern, elegant look. The precision machined perforations soften lighting, making it easy on the eyes while creating ambiance.

GLACIER PERFORATED HANGING DOWN LIGHT

Use	Downlighting Techniques in Trees or Architecture by Hanging on a Chain or Cable	
Finish	Brass, Copper, or Black Brass (Cerakote®)	
Includes	LightingShrink Professional Crimp and Heat Shrink Cable Connector	
Order With Lamp	Chameleon MR16 	GLACIER-HDL-MR16-CU-PERF-CU GLACIER-HDL-MR16-BR-PERF-BR GLACIER-HDL-MR16-BR-BLK-PERF-BR-BLK
Order Without Lamp	Fits Chameleon MR16, MR16	GLACIER-HDL-MR16-CU-PERF-CU-NL GLACIER-HDL-MR16-BR-PERF-BR-NL GLACIER-HDL-MR16-BR-BLK-PERF-BR-BLK-NL




Brass (BR)



Copper (CU)



Black Brass + Cerakote®
(BR-BLK)





GLACIER-HDL-MR16-BR-PERF-BR

INSTALLING THE LAMP

1. Unscrew the fixture body from the base.
2. Remove the stainless steel snap ring from the lamp holder.
3. Install the lamp in the socket.
4. Lay the front of the lamp inside the lamp holder and install the snap ring on the back side lip of the MR16 lamp.
5. Reinstall the lamp holder into the fixture body.

HANGING THE FIXTURE

IMPORTANT: DO NOT INSTALL ON OR NEAR ANY HIGH VOLTAGE POWER LINES

1. Hang the fixture from a secure stainless steel eye bolt, with or without a chain.
2. Create a drip loop with the wire by bending the wire to a slope one inch below the fixture cap.