


CONTENTS







SAFETY INFORMATION

Only one light bulb per socket.

Only suitable for direct mounting on non-combustible surfaces.

Under no circumstances can Delta 5" be mounted on normally flammable surfaces.


Suitable for dry, indoor use only.

Maximum ambient temperatures: 25° C

Updated 09JUN2023


DELTA 5" FLUSHMOUNT | INSTALLATION

- 01. Attach the crossbar (A) to the junction box (B) with provided screws (C) Be sure to feed the wires through the crossbar center opening.
- 02. Connect the ground wire to the crossbar with provided two port wago (D)




DELTA 5" FLUSHMOUNT | INSTALLATION


- 03. Lift the fixture (E) up to the crossbar (A), and connect the red and black wires with provided two port wagos (F).
- 04. Fit all wiring into the fixture canopy, then raise the fixture over the crossbar (A), be sure to align the canopy wedges with crossbar cleat (G) and twist counter clockwise to fit the wedges onto the crossbar cleats
- 05. Then secure the fixture with the provided two screws (H).



CONTENTS







SAFETY INFORMATION

Only one light bulb per socket.

Only suitable for direct mounting on non-combustible surfaces.

Under no circumstances can Delta 18" be mounted on normally flammable surfaces.


Suitable for dry, indoor use only.

Maximum ambient temperatures: 25° C

Updated 09JUN2023

DELTA 18" FLUSHMOUNT | INSTALLATION

- 01. Attach the crossbar (A) to the junction box (B) with provided screws (C) Be sure to feed the wires through the crossbar center opening.
- 02. Connect the ground wire to the crossbar with provided two port wago (D)



DELTA 18" FLUSHMOUNT | INSTALLATION

- 03. Lift the fixture (E) up to the crossbar (A), and connect the red and black wires with provided two port wagos (F).
- 04. Fit all wiring into the fixture canopy, then raise the fixture over the crossbar (A), be sure to align the canopy wedges with crossbar cleat (G) and twist counter clockwise to fit the wedges onto the crossbar cleats
- 05. Then secure the fixture with the provided two screws (H).

